



Single Survey

7 Duke Street Tain Ross-shire IV19 1BT





survey report on:

Customer	Jennifer & Gordon Bannerman
Customer Address	2 Hartfield Road Tain IV19 1DE
Date of Inspection	12 th September 2023
Prepared by	Angus Macaulay BSc MRICS Registered Valuer





SINGLE SURVEY TERMS AND CONDITIONS (WITH MVR)

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report onto Lender specific proforma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspected date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property.¹

If the Surveyors have had a previous business relationship within the last two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking this box.

 \boxtimes

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions of assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

¹ Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct





Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential Surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;

any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;

- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained with the Report and the generic Mortgage Valuation Report².

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, is the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

² Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.





1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property the Surveyor concludes that the property is exempt under Part 3 of the Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a Surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arms-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property"" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the Report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in Part 1 of the Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.





PART 2 – DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words: visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the Property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats, it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and Effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The Report on the location, style and condition of the Property will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion are not significant. If certain minor matters are mentioned, it should not be interpreted that the Property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the Property.

- 2.3.1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the Property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2:</u> Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 <u>Category 1:</u> No immediate action or repair is needed.

WARNING: If left unattended even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the Property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.





2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion of both the market value of the property and the reinstatement cost as defined below:

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arms-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of Market Value the Surveyor can also make various standard assumptions covering, for example, vacant possession, tenure and other legal considerations, contamination and hazardous materials, the condition of un-inspected parts, the right to use mains services, and the exclusion of curtains, carpets, etc. from the valuation. In the case of flats, the following further assumptions are made that:

- there are rights of access and exit over all communal roadways, corridors, stairways, etc. and to use communal grounds, parking areas and other facilities;
- there are no particularly troublesome or unusual legal restrictions;
- there is no current dispute between the occupiers of the flats or any outstanding claims or losses and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumptions or any found not to apply are reported.

"Reinstatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.





1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	The subjects comprise a 11/2 storey end terraced house.	
Accommodation	Ground Floor: Hall, kitchen/dining room, dark toilet and lounge.	
	First Floor: Landing, two bedrooms and bathroom.	
Gross internal floor area (m²)	87	
Neighbourhood and location	The property is situated within Tain town centre in which most local amenties can be found. The property also affords easy access to the main A9 trunk road.	
Age	Built circa 1995.	
Weather	Dry and overcast.	
Chimney stacks	Visually inspected with the aid of binoculars where appropriate.	
	N/A	
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate. Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally. Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.	
	The roof to the property is pitched, timber framed and clad on top with natural slate. The roof space was accessed by way of a trap hatch located within the first floor landing. Inspection of roof space was limited to head and shoulders only, due to lack of fixed crawl boards and insulation being laid over the top of ceiling joists.	
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.	
	Rainwater gutters and downpipes are of UPVC manufacture.	
Main walls	Visually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected.	
	Main walls to the property are of timber frame construction with render on blockwork and timber clad externally and are timber framed and faced with plasterboard internally.	
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open.	
	Windows and doors to the property are of double glazed timber casement design. The patio door is a double glazed aluminium unit.	
	External timbers are provided around the property and include the front porch/projection which is timber clad.	





External decorations	Visually inspected.
	External joinery work is provided with a stain finish.
Conservatories/porches	Visually inspected.
	N/A
Communal areas	Circulation areas visually inspected.
	N/A
Garages and permanent	Visually inspected.
outbuildings	A small timber sectional garden shed is provided. This is outwith the scope of the Home Report although the building has reached the end of its useful lifespan.
Outside areas and boundaries	Visually inspected.
	The subjects include areas of garden ground to the front which are bounded by way of timber fences and block built retaining walls. There is offstreet parking provided to the front of the property.
Ceilings	Visually inspected from floor level.
	Ceilings to the property are timber framed.
Internal walls	Visually inspected from floor level. Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Internal walls to the property are timber framed and faced with plasterboard.
Floors including sub-floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted. Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point. Physical access to the sub-floor area may be taken if the Surveyor deems it safe and reasonable to do so and subject to a minimum clearance of 1m between the floor joists and the solum as determined from the access hatch. Flooring to the property is of suspended timber and concrete with a timber floating finish over.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved. Kitchen units were visually inspected excluding appliances.
ncungs	, , , , , , , , , , , , , , , , , , , ,
	Internal joinery comprises standard internal joinery for a property of this age and type.
Chimney breasts and	The kitchen comprises floor and wall mounted units. Visually inspected. No testing of the flues or fittings was carried out.
fireplaces	
Internal decorations	N/A Visually inspected.
Internal decorations	
Cellars	The walls and ceilings are paint finished and joinery work is varnish finished. Visually inspected where there was safe and purpose-built access.
	N/A
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off the Surveyor will report this in the Report and will not turn them on.
	Mains supply. The switch gear is located within the hallway cupboard.





Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off the Surveyor will report this in the report and will not turn them on. Private supply. The LPG tank is located within the front garden.
Water, plumbing and bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances.
	Mains supply. The installation where seen comprises distribution pipework formed in copper and soil/waste pipework formed in PVC. There is a bathroom to the first floor comprising WC, wash hand basin, bath and shower cubicle with shower unit fitted. In addition, there is a ground floor toilet comprising WC and wash hand basin.
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances.
	Space heating is by way of LPG fired central heating system supplying water filled radiators throughout. Domestic hot water is also by way of gas boiler.
Drainage	Drainage covers etc were not lifted. Neither drains nor drainage systems were tested.
	Connected to the mains sewer.
Fire, smoke and burglar alarms	Visually inspected. No tests whatsoever were carried out to the system or appliances.
	Smoke detectors and a heat detector are provided.
	Fire Safety legislation effective from February 2022 requires a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat detecting alarm must be installed in every kitchen area and all smoke and heat alarms must be ceiling mounted and interlinked. Where there is a carbon-fuelled appliance, eg. central heating boiler, open fire, wood burning stove, etc a carbon monoxide detector is also required. The purchaser(s) should appraise themselves of the requirements of this legislation and engage with appropriately accredited contractors to ensure compliance.

Any additional limits to inspection

Access throughout the property was restricted due to floor coverings, furnishings and belongings. No access was gained to any sub floor areas. There are no fixed crawl boards to the roof void areas. Roof space inspection was limited to head and shoulders.

All properties built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask a specialist to undertake an appropriate test.

We have not made checks to ascertain whether the property lies within a Radon area. Further advice could be sought from UK Radon.

We have not been able to ascertain whether safety glass has been installed to glazing where required.


No checks have been made with regard to flood risk.

We have not carried out an inspection for Japanese Knotweed or other invasive plant species and unless otherwise stated for the purposes of this report we have assumed that there is no Japanese Knotweed or other invasive plant species within the boundaries of the property or in neighbouring properties. The identification of Japanese Knotweed or other invasive plant species should be made by a Specialist Contractor.





Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.





2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the following 3 categories.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacements are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Struct	ural movement
Repair Category	1
Notes	No evidence of significant ongoing settlement, subsidence or structural movement was noted. Evidence of minor cracking was detected but considered to be of longstanding, not of a serious nature at present, and in our opinion, unlikely to develop further.

Dampi	ness, rot and infestation
Repair Category	1
Notes	No significant damp, rot or infestation is apparent.

Chimn	ey stacks
Repair Category	N/A
Notes	

Roofin	g including roof space
Repair Category	1
Notes	Several chipped slates were noted. Evidence of past condensation staining was apparent in the roof space.

Rainw	rater fittings
Repair Category	1
Notes	Vegetation was noted within rainwater goods.
	It should be noted that a full assessment of the rainwater fittings can only be made during heavy rainfall.

Main v	valis
Repair Category	1
Notes	No significant defects were noted. Ivy growth to the gable should be cut back.





	- 10		
1		-0	
п		10.	- 6
	_		-8
п		- 10	- 6

Windows, external doors and joinery

Repair Category	2
Notes	Several windows and main entrance door are condensed and one window is cracked. Wet rot decay was noted to external joinery.
	We would point out that we have not tested all windows and doors.

ĺ	CK CK
-	252.00

External decorations

BASSATION .	
Repair Category	1
Notes	Weathering is apparent.



Conservatories/porches

part .	
Repair Category	N/A
Notes	



Communal areas

Repair Category	N/A
Notes	



Garages and permanent outbuildings

Repair Category	N/A
Notes	

Outside areas and boundaries	
Repair Category	2
Notes	Several coping stones are missing to block boundary walls and wet rot is affecting timber fencing. The off-street parking bay is overgrown with vegetation.

		- 14		
į	d			1
1			=	Ħ
1	=	•	Ħ	=

Ceilings

Repair Category	1
Notes	No significant defects were apparent.







Internal walls

Repair Category	1
Notes	No significant defects were apparent.



Floors including sub-floors

Repair Category 1		
Notes	Sprung flooring was noted in places.	
	It is not unusual to discover areas of past water spillage when floor coverings are removed in kitchen and bathroom compartments, revealing the need for further repair and maintenance work.	



Internal joinery and kitchen fittings

Repair Category	2
Notes	Some of the internal doors within the property have been punctured. The kitchen units are worn.



Chimney breasts and fireplaces

Repair Category	N/A	
Notes		



Internal decorations

Repair Category	2
Notes	Wear and tear was apparent to decoration finishes. Evidence of old condensation staining was also noted.



Cellars

Repair Category	N/A		
Notes			



Electricity

Repair Category	2
Notes	No significant defects were noted, however, no recent safety certificate was apparent. There is a loose power point in the lounge. The external meter box door is damaged. The extract fan is noisy and should be checked.
	The Institution of Engineering and Technology recommends that inspection and testing is undertaken at least every 10 years and on change of occupancy. It should be appreciated that only the most recently constructed or rewired properties will have installations which fully comply with present IET regulations.







Gas

Repair Category	1
Notes	No significant defects were apparent. We assume the gas supply to the house has been provided in line with good industry practice.

Water, plumbing and bathroom fittings		
Repair Category 1		
Notes	No significant defects were apparent.	
	Ongoing checks should be made to plumbing fitments and sealants. Failure of seals can result in dampness and decay to adjoining/underlying areas.	

Heating and hot water				
Repair Category	1			
Notes No significant defects were apparent.				
	We assume the heating and hot water appliances have been installed and maintained in line with the manufacturer's guidelines.			

Drainage	
Repair Category	1
Notes	No significant defects were apparent.





Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

	Structural movement	1
	Dampness, rot and infestation	1
	· · · · · · · · · · · · · · · · · · ·	_
	Chimney stacks	N/A
	Roofing including roof space	1
	Rainwater fittings	1
	Main walls	1
A	Windows, external doors and joinery	2
(B	External decorations	1
	Conservatories/porches	N/A
2	Communal areas	N/A
	Garages and permanent outbuildings	N/A
200	Outside areas and boundaries	2
	Ceilings	1
	Internal walls	1
	Floors including sub-floors	1
fall.	Internal joinery and kitchen fittings	2
THE STATE OF THE S	Chimney breasts and fireplaces	N/A
4	Internal decorations	2
	Cellars	N/A
2	Electricity	2
0	Gas	1
14	Water, plumbing and bathroom fittings	1
	Heating and hot water	1
T	Drainage	1

Repair Categories

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacements are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.





3. ACCESSIBILITY INFORMATION

Guidance Notes on Accessibility Information

<u>Three steps or fewer to a main entrance door of the property</u>: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

<u>Unrestricted parking within 25 metres</u>: For this purpose, 'unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes - parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1	Which floor(s) is the living accommodation on?	Ground & First
2	Are there three steps or fewer to a main entrance door of the property?	Yes
3	Is there a lift to the main entrance door of the property?	No
4	Are all door openings greater than 750mm?	No
5	Is there a toilet on the same level as the living room and kitchen?	Yes
6	Is there a toilet on the same level as the bedroom?	Yes
7	Are all rooms on the same level with no internal steps or stairs?	No
8	Is the unrestricted parking within 25 metres of an entrance door to the building?	Yes





4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

We assume a clear Property Enquiry Certificate shall be provided in due course and that the property has a clear Title. We further assume that any necessary statutory consents for the property in its current state are in place. If any works did require consent, then it has been assumed they meet the standards required by the Building Regulations or are exempt.

The Solicitor must also ensure that any prospective purchaser fully understands the nature, criteria and basis of a Home Report and in particular what a Home Report is and what it is not (an exhaustive Condition Report) and this should be done before any prospective purchaser makes an offer for this property based on the content of this report. If the Solicitor or purchaser requires any clarification in relation to this, they must contact the surveyor or familiarise themselves with the nature and criteria of this type of report.

It should be checked/confirmed that the tenure is absolute ownership and that there are no unduly onerous conditions or restrictive servitudes contained in the Title.

Advice should be sought with regard to the exact extent of ground pertaining to the subjects.

Where defects or repairs have been identified within this Home Report, regardless of whether reported as category 1, 2 or 3 (please read category definitions), it is always best practice to obtain detailed competitive estimates from reputable contractors or specialists prior to entering into any legally binding contract.

Estimated re-instatement cost for insurance purposes

£220,000

This figure is an opinion of an appropriate sum for which the property should be insured against total destruction on a reinstatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during reconstruction and no allowance has been made for VAT, other than on professional fees. Further discussion with your insurers is advised. The figure should be reviewed annually and in the light of any future alterations or additions.

Valuation and market comments

The market value of the property as described in this report is £120,000 (One Hundred and Twenty Thousand Pounds).

This figure assumes vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, Title restrictions or servitude rights.

The property is of a type for which there tends to be a reasonable demand. With the property market having been more buoyant in the more recent past following Covid restrictions, a number of properties are selling at figures in excess of the Home Report value. It is unclear how long these market conditions and trends will continue.

Report Author:	angus Macaulay BSc MRICS Registered Valuer		
Firm:	Torrance Partnership LLP		
Address:	165 High Street Invergordon IV18 0AL		
Electronically signed by:	Angus Macaulay BSc MRICS Registered Valuer		
Date of report:	22 nd September 2023		





Property Address: Seller's Name(s): Date of Inspection:	7 Duke Street, Tair Jennifer & Gordon 12 th September 20	Bannerman	Ref No: 15048	
			<u> </u>	
Property Details				
Property Type H	House 🖂	Detached I	f Flat/Maisonette Purpose Bui	t 🗌
Е	Bungalow 🔲	Semi Detached	Converted	
F	Flat 🔲	Mid Terrace	Floor of subject property	
N	Maisonette	End Terrace	No of floors in block	
C	Other*	*Specify under General Comments	No of Flats in block	
Type of Construction (*Specify under Ger	neral Comments)	Γraditional ⊠ *Non Traditio	nal 🗌
Tenure Absolute Owner ⊠	Leaseho	ld ☐ Age 28 ye	ars approximately	
Accommodation – (s	specify number of	rooms)		
Living Rooms 1	Bedrooms 2	Kitchens 1 Bathro	ooms 1 WCs 1 Other (Specify in Remarks)	
Gross Floor Area (exc	cluding garages & o	utbuildings) Intern		1 ²
Garage(s) / Outbuildin	ngs	Parkir	ng Space 1]	No 🗌
Residential Element –	greater than 40% `	Yes ⊠ No □	_	
Construction				
Walls Brick	☐ Stone ☐	Concrete Timber-fran	ned 🛛 Other (specify in General Rema	rks)
Roof Tile	 □ Slate ⊠	Asphalt Felt	Other (specify in General Rema	
		•		
Subsidence, Settlem		um ant?	Von ⊠ N	
Has the property suffe		ement?	Yes ⊠ N	_
If yes, is this recent or		dalaata oo kalabaaa kaasa la	Yes ∐ N	> ⊠
the immediate vicinity	-	ticipate subsidence, heave, la	andslip or flood in Yes 🔲 N	\bowtie
·		e details in General Remarks.		
Services (Based on vis the supply in General Re		f any services appear to be non-	mains, please comment on the type and lo	cation of
Drainage Mains ⊠	,	None	Mains 🛛 Private 🗌 Non-	
Gas Mains	Private 🛚	None	Mains ⊠ Private □ Non	e 🗆
Central Heating	Yes 🛚	Partial None	Brief Description LPG boiler to radiator	S
Mainly co	tial Suburb	Residential within town/city Commuter village Other	Mixed residential/commercial Remote village (Specify in General Remarks)	
Roads Made up Adopted	<u> </u>	Unmade road Unadopted	Partly completed new road Pedestrian access only	





Blood of the second					
Planning issues		.,	_		
Has the property been extended / converted / altered?		Yes	Ш	No	\bowtie
If yes, please comment in General Remarks					
General Remarks					
The property is situated within easy reach of Tain town centre in which most local amenties ca	n be found.	The pro	perty al	so affo	ords easy
access to the main A9 trunk road.					
At the time of our inspection, the property was found to be in average condition for one of its likely to be attended to under routine maintenance/modernisation/repair.	s age and ty	pe, wit	h most i	tems i	dentified
inkely to be attended to under routine maintenance/modernisation/repail.					
Minor movement cracking was noted which appears of longstanding and unlikely to develop fu	rther				
Thinly movement crucking was noted which appears of long-standing and animally to develop full	uici.				
Essential Repairs					
None.					
Estimated and of according your in Company Company	No 🗆		A		
Estimated cost of essential repairs £ Retention recommended Yes	No 📙		Amoun	[t	
Comment on Mortgageability					
We consider the property mortgageable.					
Valuations (Assuming Vacant Possession)					
Market value in present condition	£120,000				
Market value on completion of essential repairs	£				
Insurance Reinstatement value	£220,000				
(to include the cost of total rebuilding, site clearance, professional fees, ancillary	LEZU,000				
charges plus VAT)					
Is a Reinspection necessary?	Yes □	1	No 🖂		





Energy Report



Energy Performance Certificate (EPC)

Dwellings

Scotland

7 DUKE STREET, TAIN, IV19 1BT

Dwelling type: End-terrace house
Date of assessment: 12 September 2023
Date of certificate: 12 September 2023

Total floor area: 87 m²

Primary Energy Indicator: 177 kWh/m²/year

Reference number: 9323-1012-0201-0447-8200

Type of assessment: RdSAP, existing dwelling

Approved Organisation: Elmhurst


Main heating and fuel: Boiler and radiators, LPG

You can use this document to:

- . Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£4,305	See your recommendations
Over 3 years you could save*	£720	report for more information

^{*} based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (57)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (70)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Floor insulation (solid floor)	£4,000 - £6,000	£201.00
2 Low energy lighting	£25	£150.00
3 Heating controls (room thermostat)	£350 - £450	£177.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed)	****	★★★★ ☆
Roof	Roof room(s), ceiling insulated	****	★★★★ ☆
Floor	Solid, limited insulation (assumed)	_	_
Windows	Fully double glazed	***	***
Main heating	Boiler and radiators, LPG	***	★★★★ ☆
Main heating controls	Programmer, TRVs and bypass	★★★☆☆	***
Secondary heating	None	_	_
Hot water	From main system	***	★★★★ ☆
Lighting	Low energy lighting in 58% of fixed outlets	****	★★★★ ☆

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 38 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.3 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.4 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£3,123 over 3 years	£2,769 over 3 years	
Hot water	£591 over 3 years	£399 over 3 years	You could
Lighting	£591 over 3 years	£417 over 3 years	save £720
	Totals £4,305	£3,585	over 3 years


These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indicative cost	Typical saving	Rating after improvement		
		indicative cost	per year	Energy	Environment	
1 Floor insulation (solid floor	r)	£4,000 - £6,000	£67	D 59	C 72	
2 Low energy lighting for all	fixed outlets	£25	£50	D 60	C 73	
3 Upgrade heating controls		£350 - £450	£59	D 62	C 74	
4 Solar water heating		£4,000 - £6,000	£64	D 64	C 76	
5 Solar photovoltaic panels,	2.5 kWp	£3,500 - £5,500	£599	C 74	B 85	

Choosing the right improvement package





About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Floor insulation (solid floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulating solid floors can present challenges; insulation laid on top of existing solid floors may impact on existing doors and finishes whilst lifting of a solid floor to insert insulation below will require consideration of the potential effect on both structural stability and damp proofing. It is advised to seek advice from a Chartered Structural Engineer or a registered Architect about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work and may also require a building warrant so it is best to check with your local authority building standards department.

2 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

3 Heating controls (room thermostat)

The heating system should have a room thermostat to enable the boiler to switch off when no heat is required. A competent heating engineer should be asked to do this work. Insist that the thermostat switches off the boiler as well as the pump and that the thermostatic radiator valve is removed from any radiator in the same room as the thermostat. Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

4 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

5 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	8,538	(33)	N/A	N/A
Water heating (kWh per year)	1,967			

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Angus Macaulay

Assessor membership number: EES/008306

Company name/trading name: Torrance Partnership LLP Address: 165 High Street

Ross-shire Invergordon

IV18 ÖAL 01349 853151

Phone number: 01349 853151

Email address: admin@torrance-partnership.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT





Seller(s) Jennifer And Gordon Bannerman Property Address 7 Duke Street Tain IV19 1BT

Note for sellers

- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Q1: Length of Ownership				
How long have you owned the property?			15/3	
Q2: Council Tax				
Which council tax band is y	our property in?(Please Select)		С	
Q3: Parking				
Garage	×	Allocated Parking Space	34	
Driveway	✓	Shared Parking	34	
On Street	×	Resident Permit	*	
Metered Parking	×			
Other (Please Specify)				
Q4: Conservation Area				
	ated Conservation Area (that is an area of pearance of which it is desirable to preser		No	
Q5: Listed Building				
Is your property a Listed Boundary being or special architecture	uilding or contained within one(that is a buil al or historical interest)	ding recognised and approved as	No	

Created On: 17/09/2023 Page 1 of 7 Pages

Q6: Alterations/Additions/Extensions

a(i)

During your time in the property, have you carried out a structural alteration, additions or extensions(for example, provision of an extra bath\shower room, toilet, or bedroom)?

No

Please describe the changes you made

N/A

a(ii)

Did you obtain planning permission, building warrant, completion certificate and other consents for this work?

Nο

If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.

If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:

N/A

b(i)

Have you had replacement windows, doors, patio doors or double glazing installed in your property?

No

b(ii)

Were the replacements the same shape and type as the ones your replaced?

N/A

b(iii)

Did the work involve any changes to the window or door openings?

N/A

b(iiii)

Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed)

N/A

Please give any guarantees which you received for this work to you solicitor or estate agent.

Created On: 17/09/2023 Page 2 of 7 Pages

Q7: Central Heating	
a(i)	
Is there a central heating system in your property?	Yes
(Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and bathroom).	
a(ii)	
What kind of central heating is there? (Example: gas-fired, solid fuel, electric storage heating, gas warm air).	Gas
a(iii)	
When was your central heating system or partial heating system installed?	Not known
a(iiii)	
Do you have a maintenance contract for the central heating system?	Yes
Please give details of the company with which you have a maintenance contract?	Northern fires and stoves
a(iiiii)	
When was your maintenance agreement last renewed? please provide month and year	17.02.2023
Q8: Energy Performance Certificate	
Does your property have an Energy Performance Certificate which is less than 10 years old?	No
Q9: Issues that may have affected your property	
a(i)	
Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	No
is the damage the subject of any outstanding insurance claim?	N/A
b(i)	
Are you aware of the existence of asbestos in your property	No
Please give Details?	N/A

Created On: 17/09/2023 Page 3 of 7 Pages

Q10: Services

a(i)

Please tick which services are connected to your property and give details of the supplier

rease tick which services are connected to your property and give details of the supplier				
	Connected	Supplier		
Gas or Liquid Petroleum	*	N/A		
Water mains or private water supply	*	N/A		
Electricity	*	N/A		
Mains Drainage	*	N/A		
Telephone	*	N/A		
Cable TV or Satellite	*	N/A		
BroadBand	*	N/A		
b(i)				
Is there a septic tank at the property?		No		
b(ii)				
Do you have appropriate consents for the discharge from your sep	tic tank?	N/A		
b(iii)				
Do you have a maintenance contract for your septic tank?		N/A		
Please give Details?		N/A		

Created On: 17/09/2023 Page 4 of 7 Pages

Q11: Responsibilities for shared OR Common Areas

f(i)

Please give details?

a(i) Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a No shared drive, private road, boundary, or garden area? Please give details? N/A b(i) Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other No common areas? Please give details? N/A Has there been any major repair or replacement of any part of the roof during the time you have owned the Nο property? Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish No bin or to maintain your boundaries? Please give details? N/A e(i) As far as you are aware, do any of your neighbours have the right to walk over your property, for example No to put out their rubbish bin or to maintain their boundary? Please give details? N/A

As far as you are aware, is there a public right of way across your any part of your property? (public right of

N/A

way is a way over which the public las a right to pass, whether or not the land is privatly owned).

Created On: 17/09/2023 Page 5 of 7 Pages

Q12: Charges associated with your property	
a(i)	
Is there a factor or property manager for your property?	No
Please provide the name and address, and give details of any deposits held and approximate charges:	N/A
b(i)	
Is there a common buildings insurance policy?	No
Is the cost of insurance included in your monthly/annual factor's charges?	N/A
c(i)	
Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	N/A
Q13: Specialist Works	
a(i)	
As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property	No
Please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	N/A
b(i)	
As far as you are aware has any preventative work for dry rot, wet rot, or damp ever been carried out on your property?	No
Please give details:	N/A
c(i)	
Do you have guarantees relating to this work?	N/A
If you have answered yes, these guarantees will be needed by the purchaser and should be given to your sol possible for checking. If you do not have them yourself please write below who has these documents and you agent will arrange for them to be obtained. You will also need to provide a description of the work carried out the original estimate.	ur solicitor or estate
Guarantees are held by:	N/A

Created On: 17/09/2023 Page 6 of 7 Pages

V

Signature(s)

Agreed

Q14: Guarantees							
a							
Are there any guarantees or warranties for any of the following:							
Electric Work	Yes	Roofing	No				
Central Heating	No	National House Building Council (NHBC)	No				
Damp Course	No	Any other work or installations?	No				
b							
Please give any details of the	Electrical installation condition report						
С							
Are there any outstanding cla	No						
Please give details:	N/A						
Q15: Boundaries							
As far as you are aware, has	No						
please give any details.	N/A						
Q16: Notices that affect your property							
In the past three years have you ever received a notice:							
a(i)							
Advising that the owner of a n	No						
b(i)							
That affects your property in s	No						
c(i)							
That requires you to do any m	No						
if you have answered yes to any a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.							
Declaration							
Declaration by the seller(s) / or other authorised body or person(s) I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.							
	_						

Created On: 17/09/2023 Page 7 of 7 Pages

Gordon & Jennifer Bannerman