

# HOME REPORT

229 EAST TULLOCH  
BONAR BRIDGE  
ARDGAY  
IV24 3AS



**DM HALL**  
CHARTERED SURVEYORS



# ENERGY PERFORMANCE CERTIFICATE



**DM HALL**  
CHARTERED SURVEYORS



# Energy Performance Certificate (EPC)

# Scotland

Dwellings

Tulloch, 229 , Tulloch, Bonar Bridge, IV24 3AS

**Dwelling type:** Detached house  
**Date of assessment:** 08 March 2021  
**Date of certificate:** 09 March 2021  
**Total floor area:** 104 m<sup>2</sup>  
**Primary Energy Indicator:** 1059 kWh/m<sup>2</sup>/year


**Reference number:** 0588-1057-4237-4349-3220  
**Type of assessment:** RdSAP, existing dwelling  
**Approved Organisation:** Elmhurst  
**Main heating and fuel:** Electric storage heaters

## You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

|  |                |  |
|--|----------------|--|
| <b>Estimated energy costs for your home for 3 years*</b> | <b>£10,923</b> | See your recommendations report for more information |
| <b>Over 3 years you could save*</b>                      | <b>£6,792</b>  |  |

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




## Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band F (29)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



## Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO<sub>2</sub>) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band G (12)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

## Top actions you can take to save money and make your home more efficient

| Recommended measures                      | Indicative cost  | Typical savings over 3 years |
|---|------------------|------------------------------|
| 1 Flat roof or sloping ceiling insulation | £850 - £1,500    | £507.00                      |
| 2 Room-in-roof insulation                 | £1,500 - £2,700  | £2652.00                     |
| 3 Internal or external wall insulation    | £4,000 - £14,000 | £1494.00                     |

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit [greenerscotland.org](http://greenerscotland.org) or contact Home Energy Scotland on 0808 808 2282.

**THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE**

## Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

| Element               | Description   | Energy Efficiency | Environmental |
|-----------------------|---|-------------------|---------------|
| Walls                 | Granite or whinstone, as built, no insulation (assumed) | ★★☆☆☆             | ★★☆☆☆         |
|                       | Solid brick, as built, no insulation (assumed)          | ★☆☆☆☆             | ★☆☆☆☆         |
| Roof                  | Roof room(s), ceiling insulated                         | ★★☆☆☆             | ★★☆☆☆         |
| Floor                 | Solid, no insulation (assumed)                          | —                 | —             |
| Windows               | Fully double glazed                                     | ★★★★☆☆            | ★★★★☆☆        |
| Main heating          | Electric storage heaters                                | ★★★★☆☆            | ★☆☆☆☆         |
| Main heating controls | Automatic charge control                                | ★★★★☆☆            | ★★★★☆☆        |
| Secondary heating     | Room heaters, dual fuel (mineral and wood)              | —                 | —             |
| Hot water             | Electric immersion, off-peak                            | ★☆☆☆☆             | ★★☆☆☆         |
| Lighting              | Low energy lighting in 27% of fixed outlets             | ★★★★☆☆            | ★★★★☆☆        |

## The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.


## The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 187 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 19 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 14.1 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

## Estimated energy costs for this home

|               | Current energy costs | Potential energy costs | Potential future savings  |
|---------------|----------------------|------------------------|---|
| Heating       | £9,399 over 3 years  | £3,465 over 3 years    |  |
| Hot water     | £1,071 over 3 years  | £402 over 3 years      |   |
| Lighting      | £453 over 3 years    | £264 over 3 years      |   |
| <b>Totals</b> | <b>£10,923</b>       | <b>£4,131</b>          |   |

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

## Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

| Recommended measures  | Indicative cost   | Typical saving per year | Rating after improvement |             |
|---|-------------------|-------------------------|--------------------------|-------------|
|   |                   |                         | Energy                   | Environment |
| 1 Flat roof or sloping ceiling insulation                         | £850 - £1,500     | £169                    | F 31                     | G 14        |
| 2 Room-in-roof insulation   | £1,500 - £2,700   | £884                    | E 47                     | F 28        |
| 3 Internal or external wall insulation                            | £4,000 - £14,000  | £498                    | D 57                     | E 39        |
| 4 Floor insulation (solid floor)                                  | £4,000 - £6,000   | £193                    | D 61                     | E 44        |
| 5 Low energy lighting for all fixed outlets                       | £40               | £46                     | D 63                     | E 44        |
| 6 High heat retention storage heaters and dual immersion cylinder | £1,600 - £2,400   | £407                    | C 72                     | E 50        |
| 7 Solar water heating   | £4,000 - £6,000   | £66                     | C 74                     | E 53        |
| 8 Solar photovoltaic panels, 2.5 kWp                              | £3,500 - £5,500   | £301                    | B 83                     | D 61        |
| 9 Wind turbine  | £15,000 - £25,000 | £727                    | A 103                    | C 78        |

### Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- Biomass boiler (Exempted Appliance if in Smoke Control Area)
- Air or ground source heat pump

## Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to [www.greenerscotland.org](http://www.greenerscotland.org).

## About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

### **1 Flat roof or sloping ceiling insulation**

Insulating a flat roof or sloping ceiling will significantly reduce heat loss through the roof; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulation can be placed on top of the roof under the waterproof membrane and should particularly be considered when the waterproofing needs to be replaced. Further information about roof insulation and details of local contractors can be obtained from the National Insulation Association ([www.nationalinsulationassociation.org.uk](http://www.nationalinsulationassociation.org.uk)). Building regulations generally apply to this work so it is best to check with your local authority building standards department.

### **2 Room-in-roof insulation**

Insulating roof rooms will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. If it has a flat ceiling insulation can usually be added above the ceiling, and sloping ceilings and walls of roof rooms can be insulated using an internal lining board. Roof voids must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about roof room insulation and details of local contractors can be obtained from the National Insulation Association ([www.nationalinsulationassociation.org.uk](http://www.nationalinsulationassociation.org.uk)). Building regulations generally apply to this work so it is best to check this with your local authority building standards department.

### **3 Internal or external wall insulation**

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide long-lasting weather protection. Further information can be obtained from the National Insulation Association ([www.nationalinsulationassociation.org.uk](http://www.nationalinsulationassociation.org.uk)). It should be noted that a building warrant is required for the installation of external wall insulation. Planning permission may also be required and that building regulations apply to external insulation so it is best to check with your local authority on both issues.

### **4 Floor insulation (solid floor)**

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulating solid floors can present challenges; insulation laid on top of existing solid floors may impact on existing doors and finishes whilst lifting of a solid floor to insert insulation below will require consideration of the potential effect on both structural stability and damp proofing. It is advised to seek advice from a Chartered Structural Engineer or a registered Architect about this if unsure. Further information about floor insulation is available from many sources including [www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation](http://www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation). Building regulations generally apply to this work and may also require a building warrant so it is best to check with your local authority building standards department.

### **5 Low energy lighting**

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (<http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting>).

### **6 High heat retention storage heaters**

Modern storage heaters have better insulation and are easier to control than the older type in this property. Ask for a quotation for new, high heat retention heaters with automatic charge and output controls. A dual-immersion cylinder, which can be installed at the same time, will provide cheaper hot water than the system currently installed. Installations should be in accordance with the current regulations covering electrical wiring. Ask the heating engineer to explain the options, which might also include switching to other forms of electric heating.



## 7 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at [www.microgenerationcertification.org](http://www.microgenerationcertification.org).

## 8 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at [www.microgenerationcertification.org](http://www.microgenerationcertification.org).

## 9 Wind turbine

A wind turbine provides electricity from wind energy. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Wind turbines are not suitable for all properties. The system's effectiveness depends on local wind speeds and the presence of nearby obstructions, and a site survey should be undertaken by an accredited installer. Planning permission might be required and building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for a wind turbine, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at [www.microgenerationcertification.org](http://www.microgenerationcertification.org).

## Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

**LZC energy sources present:** There are none provided for this home

## Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit <https://energysavingtrust.org.uk/energy-at-home> for more information.

| Heat demand                  | Existing dwelling | Impact of loft insulation | Impact of cavity wall insulation | Impact of solid wall insulation |
|------------------------------|-------------------|---------------------------|----------------------------------|---------------------------------|
| Space heating (kWh per year) | 32,692            | (170)                     | N/A                              | (4,980)                         |
| Water heating (kWh per year) | 2,105             |                           |                                  |                                 |

## Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

## About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst ([www.elmhurstenergy.co.uk](http://www.elmhurstenergy.co.uk)), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk) and entering the report reference number (RRN) printed at the top of this page.

|                             |  |
|-----------------------------|--|
| Assessor's name:            | Mr. Calum Riach  |
| Assessor membership number: | EES/018141   |
| Company name/trading name:  | D M Hall Chartered Surveyors LLP                                   |
| Address:                    | 17 Corstorphine Road<br>Edinburgh<br>EH12 6DD                      |
| Phone number:               | 0131 477 6006  |
| Email address:              | <a href="mailto:enquiries@dmhall.co.uk">enquiries@dmhall.co.uk</a> |
| Related party disclosure:   | No related party   |

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk), with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at [www.gov.scot/epc](http://www.gov.scot/epc).

## Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit [greener-scotland.org](https://www.greener-scotland.org) or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

**HOMEENERGYSCOTLAND.ORG**  
**0808 808 2282**  
FUNDED BY THE SCOTTISH GOVERNMENT





# SINGLE SURVEY



**DM HALL**  
CHARTERED SURVEYORS



# Single Survey

survey report on:

|                         |   |
|-------------------------|---|
| <b>Property address</b> | 229 EAST TULLOCH,<br>BONAR BRIDGE,<br>ARDGAY,<br>IV24 3AS |
|-------------------------|---|

|                 |                   |
|-----------------|-------------------|
| <b>Customer</b> | Mr Douglas Murray |
|-----------------|-------------------|

|                         |   |
|-------------------------|---|
| <b>Customer address</b> | 229 EAST TULLOCH,<br>BONAR BRIDGE,<br>ARDGAY,<br>IV24 3AS |
|-------------------------|---|

|                    |             |
|--------------------|-------------|
| <b>Prepared by</b> | DM Hall LLP |
|--------------------|-------------|

|                           |                    |
|---------------------------|--------------------|
| <b>Date of inspection</b> | 11th December 2023 |
|---------------------------|--------------------|



## PART 1 - GENERAL

### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

<sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.



# Terms and Conditions

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

## 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

## 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

## 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report.<sup>2</sup>

## 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

---

<sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

# Terms and Conditions

they assign the same to any other party in writing.

## 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

## 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

## 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

## 1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;

# Terms and Conditions

- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

## PART 2 - DESCRIPTION OF THE REPORT

### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

## 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

## 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

## 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

## 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

## 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" *The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein*

# Terms and Conditions

*the parties had each acted knowledgeably, prudently and without compulsion.* In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" *is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form* unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

## 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

|  |  |
|--|--|
| <b>Description</b>                               | A detached traditional style house occupying a site extending to approximately 9 hectares.   |
| <b>Accommodation</b>                             | GROUND FLOOR: Entrance porch, hallway, living room, dining room, kitchen, side hallway with bathroom and store.<br>FIRST FLOOR: Two bedrooms.  |
| <b>Gross internal floor area (m<sup>2</sup>)</b> | 104 m  |
| <b>Neighbourhood and location</b>                | The property occupies an elevated semi rural position on the outskirts of the Village of Bonar Bridge with open views over the Kyle of Sutherland. The property is conveniently positioned for a range of local amenities and facilities.  |
| <b>Age</b>                                       | 100 + years.   |
| <b>Weather</b>                                   | Overcast with intermittent heavy rain showers.   |
| <b>Chimney stacks</b>                            | <b>Visually inspected with the aid of binoculars where appropriate.</b><br>The chimney heads are of stonework construction externally rendered and incorporating cement flashings.   |
| <b>Roofing including roof space</b>              | <b>Sloping roofs were visually inspected with the aid of binoculars where appropriate.</b><br><b>Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.</b><br><b>Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.</b><br><b>If this is not possible, then physical access to the roof space</b> |

# Single Survey

|  |   |
|--|---|
| <b>Roofing including roof space</b>        | <p><b>may be taken by other means if the Surveyor deems it safe and reasonable to do so.</b></p> <p>The main roof is pitched and clad in slates with tiled ridges. There are dormer projections to the front with flat roof decks clad in metalwork.</p> <p>No access is available to the roof space.</p> <p>The side projection has a mono pitched roof clad in profile metalwork.</p>   |
| <b>Rainwater fittings</b>                  | <p><b>Visually inspected with the aid of binoculars where appropriate.</b></p> <p>The gutters and downpipes are of a cast iron half round and round design.</p>   |
| <b>Main walls</b>                          | <p><b>Visually inspected with the aid of binoculars where appropriate.</b></p> <p><b>Foundations and concealed parts were not exposed or inspected.</b></p> <p>The property is of traditional solid stonework construction externally roughcast.</p>  |
| <b>Windows, external doors and joinery</b> | <p><b>Internal and external doors were opened and closed where keys were available.</b></p> <p><b>Random windows were opened and closed where possible.</b></p> <p><b>Doors and windows were not forced open.</b></p> <p>The windows are of a uPVC casement design, equipped with double glazed sealed units. There are timber single glazed units to the front entrance porch.</p> <p>The front and rear access doors are of a timber with single glazed panel style design.</p> |
| <b>External decorations</b>                | <p><b>Visually inspected.</b></p> <p>There are paintwork finishes throughout.</p>   |
| <b>Conservatories / porches</b>            | <p><b>Visually inspected.</b></p> <p>There is a small entrance porch to the front. This is of single leaf brickwork construction, externally roughcast and a pitched and slate clad roof.</p>   |

# Single Survey

|  |   |
|--|---|
| <b>Communal areas</b>                        | None.   |
| <b>Garages and permanent outbuildings</b>    | <p><b>Visually inspected.</b></p> <p>There is an attached stone built byre at the rear of the property. This has a pitched roof clad in corrugated iron.</p> <p>In addition there is a stone/timber and corrugated iron outbuilding attached to the righthand gable. There is also a detached 'L' shaped stone built byre which lies adjacent to the property.</p> <p>There are a number of semi dilapidated and partially collapsed timber and corrugated iron sheds within the grounds.</p> |
| <b>Outside areas and boundaries</b>          | <p><b>Visually inspected.</b></p> <p>It is understood that the property extends to approximately 9 acres of croft land. I am advised that the immediate garden grounds have been de-crofted. Boundaries where visible are formed in timber post and wire fencing. There is an overgrown access track leading to the property from the main public road.</p>   |
| <b>Ceilings</b>                              | <p><b>Visually inspected from floor level.</b></p> <p>Plasterboard, plaster lath or hardboard finishes. There are combed ceilings at first floor level.</p>   |
| <b>Internal walls</b>                        | <p><b>Visually inspected from floor level.</b></p> <p><b>Using a moisture meter, walls were randomly tested for dampness where considered appropriate.</b></p> <p>Partitions are of timber stud construction lined in lath and plaster, plasterboard or hardboard.</p>  |
| <b>Floors including sub floors</b>           | <p>Flooring at ground floor level is of solid concrete construction. There are suspended timber floors at first floor level.</p>  |
| <b>Internal joinery and kitchen fittings</b> | <p><b>Built-in cupboards were looked into but no stored items were moved.</b></p> <p><b>Kitchen units were visually inspected excluding appliances.</b></p> <p>There is a timber tread and riser staircase. The internal doors are of a timber panelled style. The kitchen fittings are limited and incorporate a Belfast sink unit along with a range of floor mounted units.</p>  |
| <b>Chimney breasts and fireplaces</b>        | <p><b>Visually inspected.</b></p> <p><b>No testing of the flues or fittings was carried out.</b></p> <p>There are open fireplaces within the living room and first floor right hand gable bedroom. The Raeburn is also vented into an original chimney breast.</p>  |




# Single Survey

|   |   |
|---|---|
| <b>Internal decorations</b>               | <b>Visually inspected.</b><br>Paint and wallpapered finishes throughout.  |
| <b>Cellars</b>                            | Not applicable.   |
| <b>Electricity</b>                        | <b>Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.</b><br><br>Mains supply. Visible cabling is of a PVC coated style and the meter and consumer unit are located within the ground floor hallway. |
| <b>Gas</b>                                | No mains supply.  |
| <b>Water, plumbing, bathroom fittings</b> | <b>Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.</b><br><br><b>No tests whatsoever were carried out to the system or appliances.</b><br><br>Mains supply. There is an enamelled sink unit within the kitchen and white three piece suite within the bathroom. Visible plumbers pipework is of PVC, copper and lead materials.  |
| <b>Heating and hot water</b>              | <b>Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.</b><br><br><b>No tests whatsoever were carried out to the system or appliances.</b><br><br>There is an electric night storage/panel radiator system. Hot water is by means of an electrical immersion heater. There is an insulated hot water cylinder located within the first floor left hand gable bedroom.   |
| <b>Drainage</b>                           | <b>Drainage covers etc were not lifted.</b><br><br><b>Neither drains nor drainage systems were tested.</b><br><br>It is assumed that drainage is connected to a private septic tank and that this is located within the site boundaries. This will however require to be confirmed.   |

|  |   |
|--|---|
| <b>Fire, smoke and burglar alarms</b>      | <p><b>Visually inspected.</b></p> <p><b>No tests whatsoever were carried out to the system or appliances.</b></p> <p>There are no smoke detectors evident.</p> <p>Legislation by the Scottish Government, which took effect from February 2022, requires all residential properties to have a system of inter-linked smoke alarms and heat detectors. Carbon monoxide detectors are also required where appropriate. Purchasers should appraise themselves of the requirements of this legislation, and engage with appropriately accredited contractors to ensure compliance.</p>  |
| <b>Any additional limits to inspection</b> | <p><b>For flats / maisonettes</b></p> <p><b>Only the subject flat and internal communal areas giving access to the flat were inspected.</b></p> <p><b>If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.</b></p> <p><b>The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.</b></p> <p>The property was unoccupied and unfurnished and the majority of floors were covered. Floor coverings restricted my inspection.</p> <p>Parts of the property, which are covered, unexposed or inaccessible, cannot be guaranteed to be free from defect.</p> <p>I have not carried out an inspection for Japanese Knotweed and unless otherwise stated, for the purposes of the valuation I have assumed that there is no Japanese Knotweed or other invasive plants within the boundaries of the property or in neighbouring properties.</p> <p>The report does not include an asbestos inspection. However asbestos was widely used in the building industry until around 2000, when it became a banned substance. If the possibility of asbestos based products has been reported within the limitations of the inspection and you have concerns you should engage a qualified asbestos surveyor.</p> <p>Random testing for dampness was undertaken internally with the use of a moisture meter where accessible and considered appropriate.</p> <p>In accordance with Health and Safety guidelines I have not disturbed insulation, furniture or personal effects (particularly in cupboards). Floor coverings have not been moved.</p> <p>My inspection of the roof covering was restricted from ground level and some parts were not visible. (Trees/surrounding buildings/site topography) partially blocked sight lines. The flat roof coverings were not visible from ground level.</p> <p>Concealed areas beneath and around bath/shower trays were not</p> |

|  |   |
|--|---|
| <b>Any additional limits to inspection</b> | <p>visible. Water spillage in these areas can often be discovered unexpectedly with resultant damage to concealed parts of the fabric.</p> <p>The inspection is not a fire or life safety risk assessment and should not be relied on as a risk assessment inspection. Further advice should be sought if a specific risk assessment of the property and building that it forms part of is required.</p> <p>Where repairs are required at height compliance with Health and Safety legislation often requires the use of scaffolding which can significantly impact on the cost of repair. Pricing repairs is out with the remit of this report but it would be prudent to consider costs and budgeting before offering. The various trades can advise further.</p> |
|--|---|

## Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

# Single Survey

## 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

| Category 3   | Category 2  | Category 1                               |
|--|---|--|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |



### Structural movement

|                        |   |
|------------------------|---|
| <b>Repair category</b> | 1   |
| <b>Notes</b>           | The property has been affected by previous movement. Rough cast cracking is evident but within the limitations of the inspection there was no evidence to suggest that this is ongoing. |



### Dampness, rot and infestation

|                        |   |
|------------------------|---|
| <b>Repair category</b> | 3   |
| <b>Notes</b>           | <p>There is evidence of dampness at the base of various walls and concealed timbers may be defective. Further investigation can be carried out by a firm of timber/damp specialists with a view to having all necessary remedial repair work implemented.</p> <p>There is evidence of penetrating dampness to various walls and concealed timbers may be defective. Further investigation can be carried out by a firm of timber/damp specialists with a view to having all necessary remedial repairs implemented.</p> <p>External ground levels are high in areas and this can contribute to timber/damp defects. Ground levels should be lowered to a suitable level beneath internal floor levels. A specialist contractor can advise.</p> <p>There is evidence of wood boring insect infestation. This can be treated by a timber/specialist contractor.</p> |



### Chimney stacks

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 3  |
| <b>Notes</b>           | There are large sections of missing render to the left hand gable stack. Exposed stonework is also badly weathered. A building contractor can advise further however the stack may require to be demolished and rebuilt. |



## Roofing including roof space

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 3  |
| <b>Notes</b>           | <p>There are a number of broken and loose slates together with water ingress at first floor level. A reputable roofing contractor can be asked to inspect the roof structure to advise on all necessary repairs to ensure wind and water tightness. Inspection at close quarters may reveal further deterioration/damage to roofing materials, especially where these are original. Regular maintenance is anticipated until replacement.</p> <p>Natural slates have an expected lifespan of up to 100 years or more depending on slate quality, source, thickness and cutting skill of the slater. Slates will deteriorate over time; nail fixings will corrode and loosen resulting in on-going maintenance requirements. Close quarter and disruptive inspections may reveal damage to roofing materials, especially where these are original. Regular maintenance should be anticipated particularly after adverse weather conditions.</p> <p>There is extensive water ingress around flat roof sections. I suspect that existing coverings have reached the end of their lifespan and checks at close quarters will require to be undertaken by a competent roofing contractor and estimates obtained for their repair/replacement. Flat roof coverings have a limited life expectancy.</p> |



## Rainwater fittings

|                        |   |
|------------------------|---|
| <b>Repair category</b> | 3   |
| <b>Notes</b>           | <p>Metal rainwater fittings are corroded in places. These should be treated and redecorated. Metal rainwater fittings require regular maintenance.</p> <p>Rainwater fittings are in a poor state of repair and require overhaul or replacement.</p> <p>Gutters are blocked in places and should be cleared.</p> <p>There is evidence of some leakage from rainwater fittings and affected sections should be (repaired/replaced).</p> |



## Main walls

|                        |   |
|------------------------|---|
| <b>Repair category</b> | 2   |
| <b>Notes</b>           | <p>The rendering of outer walls is cracked, worn and bossed in places and can be repaired or replaced by a competent local builder.</p> |



## Windows, external doors and joinery

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 2  |
| <b>Notes</b>           | <p>External joinery including window frames/doors/door frames/eaves timbers are affected by decay to varying degrees. A reputable joiner can advise on all necessary repairs.</p> <p>The window units are of an older type. The seals to older double glazed units</p> |





## Windows, external doors and joinery

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 2  |
| <b>Notes</b>           | often fail resulting in condensation between the panes of glass. Failed sealed units can go undetected in certain weather/daylighting conditions and such failings are not considered to be significant because the window remains functional albeit not as double glazing. This can occur without warning and may only be seen in certain weather conditions. |



## External decorations

|                        |   |
|------------------------|---|
| <b>Repair category</b> | 2   |
| <b>Notes</b>           | Outside paintwork has deteriorated and redecoration is now required. Regular re-painting of external joinery will prolong its lifespan. |



## Conservatories/porches

|                        |   |
|------------------------|---|
| <b>Repair category</b> | 2   |
| <b>Notes</b>           | Decay is evident to external timbers. Repairs will be required to affected areas. There is dampness to wall linings which will require further investigation. |



## Communal areas

|                        |                 |
|------------------------|-----------------|
| <b>Repair category</b> | -               |
| <b>Notes</b>           | Not applicable. |



## Garages and permanent outbuildings

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 3  |
| <b>Notes</b>           | <p>There is evidence of wood boring insect infestation within the outbuildings. Dampness and water penetration is also evident to the majority. Decay is evident to rainwater fittings.</p> <p>There is corrosion to roof coverings. The attached corrugated iron clad outbuildings are in a particularly poor state of repair and I consider near the end of their useful life.</p> |



## Outside areas and boundaries

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 2  |
| <b>Notes</b>           | The access track from the main public road is overgrown and will require to be upgraded. |



## Outside areas and boundaries

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 2  |
| <b>Notes</b>           | <p>There is damage to boundary fencing.</p> <p>The garden grounds are overgrown and the croft land uncultivated.</p> |



## Ceilings

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 3  |
| <b>Notes</b>           | <p>There are large areas of defective plasterwork as a result of water ingress and repairs/replacement are required.</p> <p>There are polystyrene ceiling tiles to a number of ceiling surfaces. This may represent a fire hazard.</p> |



## Internal walls

|                        |   |
|------------------------|---|
| <b>Repair category</b> | 3   |
| <b>Notes</b>           | <p>There is high dampness to wall linings at ground and first floor levels. Please see Dampness, Rot and Infestation section above.</p> |



## Floors including sub-floors

|                        |   |
|------------------------|---|
| <b>Repair category</b> | 3   |
| <b>Notes</b>           | <p>Dampness is evident to solid concrete finishes at ground floor level and further investigation and repair will be required.</p> <p>Woodworm is evident to timber floors at first floor level. Please see Dampness, Rot and Infestation section above.</p> <p>Sections of flooring are loose/uneven.</p> <p>It is not unusual to discover areas of past water spillage when floor coverings are removed in kitchen and bathroom compartments, revealing the need for further repair and maintenance work.</p> |



## Internal joinery and kitchen fittings

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 3  |
| <b>Notes</b>           | <p>Kitchen base and wall units are dated and reaching the end of their useful life.</p> <p>Glazed inserts to interior doors may not be of appropriate toughened glass or meet the recognised Building Standards.</p> <p>Woodworm is evident to joinery finishes. Please see Dampness, Rot and Infestation section above.</p> |





## Chimney breasts and fireplaces

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 3  |
| <b>Notes</b>           | <p>There is evidence of dampness to the flue lines and chimney breasts and the possibility of further concealed defects exists. Further investigation and repair is required.</p> <p>Where fireplaces have been removed there is limited provision for ventilation. Unventilated chimney breasts can result in condensation. Disused chimneys should be capped and vented.</p> <p>If disused fireplaces are to be reopened further advice should be sought to ensure that the chimney flue is intact and suitable for use.</p> |



## Internal decorations

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 3  |
| <b>Notes</b>           | Decorative finishes are (very) dated and complete redecoration is envisaged. |



## Cellars

|                        |                 |
|------------------------|-----------------|
| <b>Repair category</b> | -               |
| <b>Notes</b>           | Not applicable. |



## Electricity

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 2  |
| <b>Notes</b>           | <p>The electric circuits and systems are of mixed ages and styles. Further advice will be available from a NICEIC/SELECT registered electrician.</p> <p>It is recommended that all electrical installations be checked every five years or on change of ownership to keep up to date with frequent changes in Safety Regulations. Further advice will be available from a qualified NICEIC/ SELECT registered Contractor. It should be appreciated that only recently constructed or rewired properties will have installations which fully comply with IET regulations.</p> |



## Gas

|                        |                 |
|------------------------|-----------------|
| <b>Repair category</b> | -               |
| <b>Notes</b>           | Not applicable. |



## Water, plumbing and bathroom fittings

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 2  |
| <b>Notes</b>           | <p>Sections of lead supply pipework should be replaced.</p> <p>There is evidence of (leakage/spillage) around sanitary fittings and a consequent risk of damage to the concealed fabric. Further investigation and repair can be undertaken by a timber/damp specialist (and/or) plumbing contractor with a view to having all necessary remedial repair work implemented.</p> |



## Heating and hot water

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 2  |
| <b>Notes</b>           | <p>The central heating system is of an older style. A Gas Safe registered contractor can advise further.</p> <p>Corrosion is evident to electric night storage heaters and further advice should be sought.</p> <p>It is assumed that the central heating system has been properly installed and maintained to meet with all relevant regulations, particularly in respect of flue and ventilation requirements.</p> |



## Drainage

|                        |  |
|------------------------|--|
| <b>Repair category</b> | 1  |
| <b>Notes</b>           | <p>The owner has not been able to provide any information about the septic tank maintenance and it is assumed that the tank is registered with SEPA. Regular inspection and maintenance should be anticipated.</p> |

# Single Survey

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

|                                       |   |
|---------------------------------------|---|
| Structural movement                   | 1 |
| Dampness, rot and infestation         | 3 |
| Chimney stacks                        | 3 |
| Roofing including roof space          | 3 |
| Rainwater fittings                    | 3 |
| Main walls                            | 2 |
| Windows, external doors and joinery   | 2 |
| External decorations                  | 2 |
| Conservatories/porches                | 2 |
| Communal areas                        | - |
| Garages and permanent outbuildings    | 3 |
| Outside areas and boundaries          | 2 |
| Ceilings                              | 3 |
| Internal walls                        | 3 |
| Floors including sub-floors           | 3 |
| Internal joinery and kitchen fittings | 3 |
| Chimney breasts and fireplaces        | 3 |
| Internal decorations                  | 3 |
| Cellars                               | - |
| Electricity                           | 2 |
| Gas                                   | - |
| Water, plumbing and bathroom fittings | 2 |
| Heating and hot water                 | 2 |
| Drainage                              | 1 |

## Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

## Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

## Category 1

No immediate action or repair is needed.

### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

## 3. Accessibility information

### Guidance notes on accessibility information

*Three steps or fewer to a main entrance door of the property:*

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

*Unrestricted parking within 25 metres:*

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

|   |   |
|---|---|
| <b>1. Which floor(s) is the living accommodation on?</b>                                      | Ground and First.   |
| <b>2. Are there three steps or fewer to a main entrance door of the property?</b>             | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |
| <b>3. Is there a lift to the main entrance door of the property?</b>                          | Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> |
| <b>4. Are all door openings greater than 750mm?</b>   | Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> |
| <b>5. Is there a toilet on the same level as the living room and kitchen?</b>                 | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |
| <b>6. Is there a toilet on the same level as a bedroom?</b>                                   | Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> |
| <b>7. Are all rooms on the same level with no internal steps or stairs?</b>                   | Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> |
| <b>8. Is there unrestricted parking within 25 metres of an entrance door to the building?</b> | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |

## 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

### Matters for a solicitor or licensed conveyancer

Drainage is to a septic tank. It is assumed that the tank is registered with SEPA. The position regarding age, location, condition and maintenance history should be clarified.

It is understood that the house and immediate garden grounds have been de-crofted and that the remainder is held under crofting tenure. Your legal representatives will require to confirm full details.

There is an unmade private access road leading to the property. It is assumed that this serves the subject property only with no rights of access for third parties.

### Estimated reinstatement cost for insurance purposes

£325,000 (THREE HUNDRED AND TWENTY FIVE THOUSAND POUNDS).

The above figure is for the house only and specialist advice should be sought on the re- instatement cost for the outbuildings.

It should be noted this sum is an estimate calculated by using a rate per square metre based on information provided by Building Cost Information Service (BCIS).

### Valuation and market comments

£200,000 (TWO HUNDRED THOUSAND POUNDS).

Against a backdrop of changing economic circumstances and increasing interest rates, it is not possible to predict how the market will perform in the coming months although market conditions continue to be stable at present.

The opinion of Market Value is provided on the assumption that the cost of Category 3 repairs will not exceed £25,000. I reserve the right to re-consider the reported Market Value if subsequent estimates exceed this figure.

|                       |   |
|-----------------------|---|
| <b>Signed</b>         | Security Print Code [611562 = 0321 ]<br>Electronically signed                 |
| <b>Report author</b>  | Graham Forbes   |
| <b>Company name</b>   | DM Hall LLP   |
| <b>Address</b>        | Hope House, Castlehill Drive, Cradlehall Business Park, Inverness,<br>IV2 5GH |
| <b>Date of report</b> | 15th January 2024   |

# Mortgage Valuation Report



## Property Address

Address 229 EAST TULLOCH, BONAR BRIDGE, ARDGAY, IV24 3AS  
Seller's Name Mr Douglas Murray  
Date of Inspection 11th December 2023

## Property Details

Property Type  House  Bungalow  Chalet  Purpose built maisonette  
 Coach  Studio  Converted maisonette  Purpose built flat  
 Converted flat  Tenement flat  Flat over non-residential use  Other (specify in General Remarks)

Property Style  Detached  Semi detached  Mid terrace  End terrace  
 Back to back  High rise block  Low rise block  Other (specify in General Remarks)

Does the surveyor believe that the property was built for the public sector, e.g. local authority, military, police?  Yes  No

Flats/Maisonettes only Floor(s) on which located  No. of floors in block  Lift provided?  Yes  No  
No. of units in block

Approximate Year of Construction

## Tenure

Absolute Ownership  Leasehold Ground rent £  Unexpired years

## Accommodation

Number of Rooms  Living room(s)  Bedroom(s)  Kitchen(s)  
 Bathroom(s)  WC(s)  Other (Specify in General remarks)

Gross Floor Area (excluding garages and outbuildings)  m<sup>2</sup> (Internal)  m<sup>2</sup> (External)

Residential Element (greater than 40%)  Yes  No

## Garage / Parking / Outbuildings

Single garage  Double garage  Parking space  No garage / garage space / parking space  
Available on site?  Yes  No

Permanent outbuildings:

Attached stone built byre.  
Detached 'L' shaped stone built byre.  
Attached stone and timber/corrugated iron byre.

# Mortgage Valuation Report

## Construction

Walls  Brick  Stone  Concrete  Timber frame  
 Solid  Cavity  Steel frame  Concrete block  Other (specify in General Remarks)

Roof  Tile  Slate  Asphalt  Felt  
 Lead  Zinc  Artificial slate  Flat glass fibre  Other (specify in General Remarks)

## Special Risks

Has the property suffered structural movement?  Yes  No  
If Yes, is this recent or progressive?  Yes  No  
Is there evidence, history, or reason to anticipate subsidence, heave, landslip or flood in the immediate vicinity?  Yes  No  
If Yes to any of the above, provide details in General Remarks.

## Service Connection

Based on visual inspection only. If any services appear to be non-mains, please comment on the type and location of the supply in General Remarks.

Drainage  Mains  Private  None  
Electricity  Mains  Private  None  
Central Heating  Yes  Partial  None

Water  Mains  Private  None  
Gas  Mains  Private  None

Brief description of Central Heating:

Electric night storage/panel system.

## Site

Apparent legal issues to be verified by the conveyancer. Please provide a brief description in General Remarks.

Rights of way  Shared drives / access  Garage or other amenities on separate site  Shared service connections  
 Agricultural land included with property  Ill-defined boundaries  Other (specify in General Remarks)

## Location

Residential suburb  Residential within town / city  Mixed residential / commercial  Mainly commercial  
 Commuter village  Remote village  Isolated rural property  Other (specify in General Remarks)

## Planning Issues

Has the property been extended / converted / altered?  Yes  No

If Yes provide details in General Remarks.

## Roads

Made up road  Unmade road  Partly completed new road  Pedestrian access only  Adopted  Unadopted

# Mortgage Valuation Report

## General Remarks

The property is along older dated lines and is now at a stage where a programme of modernisation and upgrading is required. We have reflected the current state of repair in arriving at our opinion of value.

Drainage is connected to a private septic tank. It is assumed that this has been registered with SEPA and is located within the site boundaries.

The property includes approximately 9 hectares of croft land. This has specifically been excluded from our undernoted value. I am advised however that the house and immediate garden grounds have been de-crofted. Your legal representatives will require to confirm full details.

The insurance figure reported is for the house only and specialist advice should be sought on the re-instatement cost for the outbuildings.

## Essential Repairs

1. Rebuild left hand gable chimney stack.
2. Timber and damp specialist contractor to investigate dampness, decay and woodworm infestation.

Estimated cost of essential repairs £

Retention recommended?  Yes  No

Amount £



# Mortgage Valuation Report

## Comment on Mortgageability

The property will provide adequate security for mortgage purposes.

## Valuations

Market value in present condition £ 150,000  
Market value on completion of essential repairs £ 175,000  
Insurance reinstatement value £ 325,000  
(to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)  
Is a reinspection necessary?  Yes  No

## Buy To Let Cases

What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis? £   
Is the property in an area where there is a steady demand for rented accommodation of this type?  Yes  No

## Declaration

Signed Security Print Code [611562 = 0321 ]  
Electronically signed by:-  
Surveyor's name Graham Forbes  
Professional qualifications MRICS  
Company name DM Hall LLP  
Address Hope House, Castlehill Drive, Cradlehall Business Park, Inverness, IV2 5GH  
Telephone 01463 241077  
Fax 01463 233627  
Report date 15th January 2024



# PROPERTY QUESTIONNAIRE



**DM HALL**  
CHARTERED SURVEYORS



# Property Questionnaire

|                         |   |
|-------------------------|---|
| <b>Property address</b> | 229 EAST TULLOCH,<br>BONAR BRIDGE,<br>ARDGAY,<br>IV24 3AS |
|-------------------------|---|

|                  |                   |
|------------------|-------------------|
| <b>Seller(s)</b> | Mr Douglas Murray |
|------------------|-------------------|

|  |                 |
|--|-----------------|
| <b>Completion date of property questionnaire</b> | 10 January 2024 |
|--|-----------------|

# Property Questionnaire

## Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

## Information to be given to prospective buyer(s)

|           |   |   |
|-----------|---|---|
| <b>1.</b> | <b>Length of ownership</b>  |   |
|           | How long have you owned the property?   | 2 years                                 |
| <b>2.</b> | <b>Council tax</b>  |   |
|           | Which Council Tax band is your property in? (Please circle)   |   |
|           | A    B <b>Ⓒ</b> D    E    F    G    H   |   |
| <b>3.</b> | <b>Parking</b>  |   |
|           | <p>What are the arrangements for parking at your property?</p> <p>(Please tick all that apply)</p> <ul style="list-style-type: none"> <li>• Garage <input type="checkbox"/></li> <li>• Allocated parking space <input type="checkbox"/></li> <li>• Driveway <input checked="" type="checkbox"/></li> <li>• Shared parking <input type="checkbox"/></li> <li>• On street <input type="checkbox"/></li> <li>• Resident permit <input type="checkbox"/></li> <li>• Metered parking <input type="checkbox"/></li> <li>• Other (please specify): <input style="width: 400px;" type="text"/></li> </ul> |   |
| <b>4.</b> | <b>Conservation area</b>  |   |
|           | Is your property in a designated Conservation Area (i.e. an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?   | <b>Yes / No / <del>Don't know</del></b> |

# Property Questionnaire

|           |  |                 |
|-----------|--|-----------------|
| <b>5.</b> | <b>Listed buildings</b>  |                 |
|           | Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)?  | <b>Yes / No</b> |
| <b>6.</b> | <b>Alterations/additions/extensions</b>  |                 |
| <b>a.</b> | <p>(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?</p> <p><u>If you have answered yes</u>, please describe below the changes which you have made:</p>  | <b>Yes / No</b> |
|           | <p>(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?</p> <p><u>If you have answered yes</u>, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.</p> <p>If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:</p> | <b>Yes / No</b> |
| <b>b.</b> | <p>Have you had replacement windows, doors, patio doors or double glazing installed in your property?</p> <p><u>If you have answered yes</u>, please answer the three questions below:</p>   | <b>Yes / No</b> |
|           | (i) Were the replacements the same shape and type as the ones you replaced?  | <b>Yes / No</b> |
|           | (ii) Did this work involve any changes to the window or door openings?   | <b>Yes / No</b> |
|           | <p>(iii) Please describe the changes made to the windows, doors or patio doors (with approximate dates when the work was completed):</p> <p>Please give any guarantees which you received for this work to your solicitor or estate agent.</p>   |                 |
|           |  |                 |

# Property Questionnaire

|   |  |  |
|---|--|--|
| <b>7. Central heating</b>                             |  |  |
| a.  | <p>Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and the bathroom).</p> <p><b>If you have answered yes / partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).</b></p> <p>electric night storage/panel radiator system</p> <p><b>If you have answered yes, please answer the three questions below:</b></p> | <b>Yes / No / Partial</b>              |
| b.  | When was your central heating system or partial central heating system installed?  | Unknown as inherited property          |
| c.  | <p>Do you have a maintenance contract for the central heating system?</p> <p><b>If you have answered yes, please give details of the company with which you have a maintenance contract:</b></p>   | <b>Yes / No</b>                        |
| d.  | When was your maintenance agreement last renewed? (Please provide the month and year).   |  |
| <b>8. Energy Performance Certificate</b>              |  |  |
|   | Does your property have an Energy Performance Certificate which is less than 10 years old?   | <b>Yes / No</b>                        |
| <b>9. Issues that may have affected your property</b> |  |  |
| a.  | <p>Has there been any storm, flood, fire or other structural damage to your property while you have owned it?</p> <p><b>If you have answered yes, is the damage the subject of any outstanding insurance claim?</b></p>  | <b>Yes / No</b><br><br><b>Yes / No</b> |
| b.  | <p>Are you aware of the existence of asbestos in your property?</p> <p><b>If you have answered yes, please give details:</b></p>   | <b>Yes / No</b>                        |
|   |  |  |



# Property Questionnaire

| 10.                                | Services  |                                  |          |           |          |                            |   |  |                                    |   |                  |             |   |  |                |   |  |           |   |  |                      |   |  |           |   |  |
|------------------------------------|---|----------------------------------|----------|-----------|----------|----------------------------|---|--|------------------------------------|---|------------------|-------------|---|--|----------------|---|--|-----------|---|--|----------------------|---|--|-----------|---|--|
| a.                                 | <p>Please tick which services are connected to your property and give details of the supplier:</p> <table border="1" data-bbox="309 383 1374 1077"> <thead> <tr> <th>Services</th> <th>Connected</th> <th>Supplier</th> </tr> </thead> <tbody> <tr> <td>Gas / liquid petroleum gas</td> <td style="text-align: center;">—</td> <td></td> </tr> <tr> <td>Water mains / private water supply</td> <td style="text-align: center;">✓</td> <td>Highland Council</td> </tr> <tr> <td>Electricity</td> <td style="text-align: center;">—</td> <td></td> </tr> <tr> <td>Mains drainage</td> <td style="text-align: center;">—</td> <td></td> </tr> <tr> <td>Telephone</td> <td style="text-align: center;">—</td> <td></td> </tr> <tr> <td>Cable TV / satellite</td> <td style="text-align: center;">—</td> <td></td> </tr> <tr> <td>Broadband</td> <td style="text-align: center;">—</td> <td></td> </tr> </tbody> </table> |                                  | Services | Connected | Supplier | Gas / liquid petroleum gas | — |  | Water mains / private water supply | ✓ | Highland Council | Electricity | — |  | Mains drainage | — |  | Telephone | — |  | Cable TV / satellite | — |  | Broadband | — |  |
| Services                           | Connected   | Supplier                         |          |           |          |                            |   |  |                                    |   |                  |             |   |  |                |   |  |           |   |  |                      |   |  |           |   |  |
| Gas / liquid petroleum gas         | —   |                                  |          |           |          |                            |   |  |                                    |   |                  |             |   |  |                |   |  |           |   |  |                      |   |  |           |   |  |
| Water mains / private water supply | ✓   | Highland Council                 |          |           |          |                            |   |  |                                    |   |                  |             |   |  |                |   |  |           |   |  |                      |   |  |           |   |  |
| Electricity                        | —   |                                  |          |           |          |                            |   |  |                                    |   |                  |             |   |  |                |   |  |           |   |  |                      |   |  |           |   |  |
| Mains drainage                     | —   |                                  |          |           |          |                            |   |  |                                    |   |                  |             |   |  |                |   |  |           |   |  |                      |   |  |           |   |  |
| Telephone                          | —   |                                  |          |           |          |                            |   |  |                                    |   |                  |             |   |  |                |   |  |           |   |  |                      |   |  |           |   |  |
| Cable TV / satellite               | —   |                                  |          |           |          |                            |   |  |                                    |   |                  |             |   |  |                |   |  |           |   |  |                      |   |  |           |   |  |
| Broadband                          | —   |                                  |          |           |          |                            |   |  |                                    |   |                  |             |   |  |                |   |  |           |   |  |                      |   |  |           |   |  |
| b.                                 | <p>Is there a septic tank system at your property?<br/>           If you have answered yes, please answer the two questions below:</p>  | Yes / No                         |          |           |          |                            |   |  |                                    |   |                  |             |   |  |                |   |  |           |   |  |                      |   |  |           |   |  |
| c.                                 | (i) Do you have appropriate consents for the discharge from your septic tank?   | <del>Yes</del> / No / Don't know |          |           |          |                            |   |  |                                    |   |                  |             |   |  |                |   |  |           |   |  |                      |   |  |           |   |  |
| d.                                 | (ii) Do you have a maintenance contract for your septic tank?<br>If you have answered yes, please give details of the company with which you have a maintenance contract:   | <del>Yes</del> / No              |          |           |          |                            |   |  |                                    |   |                  |             |   |  |                |   |  |           |   |  |                      |   |  |           |   |  |
|                                    |   |                                  |          |           |          |                            |   |  |                                    |   |                  |             |   |  |                |   |  |           |   |  |                      |   |  |           |   |  |

# Property Questionnaire

|            |   |                                      |
|------------|---|--------------------------------------|
| <b>11.</b> | <b>Responsibilities for Shared or Common Areas</b>  |                                      |
| a.         | <p>Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?</p> <p><u>If you have answered yes, please give details:</u></p>   | <del>Yes / No / Don't Know</del>     |
| b.         | <p>Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?</p> <p><u>If you have answered yes, please give details:</u></p>  | <del>Yes / No / Not applicable</del> |
| c.         | <p>Has there been any major repair or replacement of any part of the roof during the time you have owned the property?</p>  | <del>Yes / No</del>                  |
| d.         | <p>Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries?</p> <p><u>If you have answered yes, please give details:</u></p>   | <del>Yes / No</del>                  |
| e.         | <p>As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?</p> <p><u>If you have answered yes, please give details:</u></p>   | <del>Yes / No</del>                  |
| f.         | <p>As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)</p> <p><u>If you have answered yes, please give details:</u></p> | <del>Yes / No</del>                  |
| <b>12.</b> | <b>Charges associated with your property</b>  |                                      |
| a.         | <p>Is there a factor or property manager for your property?</p> <p><u>If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:</u></p>  | <del>Yes / No</del>                  |
|            |   |                                      |

# Property Questionnaire

|                                    |   |   |
|------------------------------------|---|---|
| b.                                 | <p>Is there a common buildings insurance policy?</p> <p>If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?</p>  | <p><del>Yes / No / Don't Know</del></p> <p><del>Yes / No / Don't Know</del></p> |
| c.                                 | <p>Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.</p>   |   |
| <p><b>13. Specialist works</b></p> |   |   |
| a.                                 | <p>As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?</p> <p>If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property:</p>   | <p><del>Yes / No</del></p>  |
| b.                                 | <p>As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?</p> <p>If you have answered yes, please give details:</p>   | <p><del>Yes / No</del></p>  |
| c.                                 | <p>If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?</p> <p>If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.</p> <p>Guarantees are held by:</p> | <p><del>Yes / No</del></p>  |
|                                    |   |   |

# Property Questionnaire

|              |   |           |            |                   |                         |                              |                       |
|--------------|---|-----------|------------|-------------------|-------------------------|------------------------------|-----------------------|
| <b>14.</b>   | <b>Guarantees</b>   |           |            |                   |                         |                              |                       |
| <b>a.</b>    | <b>Are there any guarantees or warranties for any of the following:</b>   |           |            |                   |                         |                              |                       |
| <b>(i)</b>   | <b>Electrical work</b>  | <b>No</b> | <b>Yes</b> | <b>Don't know</b> | <b>With title deeds</b> | <b>Lost</b>                  | <b>Cannot Answer*</b> |
| <b>(ii)</b>  | <b>Roofing</b>  | <b>No</b> | <b>Yes</b> | <b>Don't know</b> | <b>With title deeds</b> | <b>Lost</b>                  | <b>Cannot Answer*</b> |
| <b>(iii)</b> | <b>Central heating</b>  | <b>No</b> | <b>Yes</b> | <b>Don't know</b> | <b>With title deeds</b> | <b>Lost</b>                  | <b>Cannot Answer*</b> |
| <b>(iv)</b>  | <b>NHBC</b>   | <b>No</b> | <b>Yes</b> | <b>Don't know</b> | <b>With title deeds</b> | <b>Lost</b>                  | <b>Cannot Answer*</b> |
| <b>(v)</b>   | <b>Damp course</b>  | <b>No</b> | <b>Yes</b> | <b>Don't know</b> | <b>With title deeds</b> | <b>Lost</b>                  | <b>Cannot Answer*</b> |
| <b>(vi)</b>  | <b>Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)</b>   | <b>No</b> | <b>Yes</b> | <b>Don't know</b> | <b>With title deeds</b> | <b>Lost</b>                  | <b>Cannot Answer*</b> |
| <b>b.</b>    | <b>If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):</b>              |           |            |                   |                         |                              |                       |
| <b>c.</b>    | <b>Are there any outstanding claims under any of the guarantees listed above?</b><br><b>If you have answered yes, please give details:</b>                  |           |            |                   |                         | <b>Yes / No</b>              |                       |
| <b>15.</b>   | <b>Boundaries</b>   |           |            |                   |                         |                              |                       |
|              | <b>So far as you are aware, has any boundary of your property been moved in the last 10 years?</b><br><b>If you have answered yes, please give details:</b> |           |            |                   |                         | <b>Yes / No / Don't know</b> |                       |
|              |   |           |            |                   |                         |                              |                       |

# Property Questionnaire

|            |  |                              |
|------------|--|------------------------------|
| <b>16.</b> | <b>Notices that affect your property</b>   |                              |
|            | <b>In the past 3 years have you ever received a notice:</b>  |                              |
| <b>a.</b>  | <b>advising that the owner of a neighbouring property has made a planning application?</b>   | <b>Yes / No / Don't know</b> |
| <b>b.</b>  | <b>that affects your property in some other way?</b>   | <b>Yes / No / Don't know</b> |
| <b>c.</b>  | <b>that requires you to do any maintenance, repairs or improvements to your property?</b>  | <b>Yes / No / Don't know</b> |
|            | <b>If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.</b> |                              |

**Declaration by the seller(s)/or other authorised body or person(s)**

**I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.**

**Signature(s):** \_\_\_\_\_

\_\_\_\_\_

**Date:** \_\_\_\_\_

\_\_\_\_\_





## ABERDEEN

aberdeen\_residential@  
dmhall.co.uk  
01224 594172

## AYR

ayr@dmhall.co.uk  
01292 286974

## DUMFRIES

dumfries@dmhall.co.uk  
01387 254318

## DUNDEE

dundee@dmhall.co.uk  
01382 873100

## DUNFERMLINE

dunfermline@dmhall.co.uk  
01383 621262

## EDINBURGH

edinburghresidential@  
dmhall.co.uk  
0131 624 6600

## ELGIN

elgin@dmhall.co.uk  
01343 548501

## FALKIRK

falkirk@dmhall.co.uk  
01324 628321

## GALASHIELS

galashiels@dmhall.co.uk  
01896 752009

## GLASGOW (Residential)

glasgowresidential@  
dmhall.co.uk  
0141 636 4141

## HAMILTON

hamilton@dmhall.co.uk  
01698 284939

## INVERNESS

inverness@dmhall.co.uk  
01463 241077

## INVERURIE

inverurie@dmhall.co.uk  
01467 624393

## IRVINE

irvine@dmhall.co.uk  
01294 311070

## KIRKCALDY

kirkcaldy@dmhall.co.uk  
01592 598200

## LIVINGSTON

livingston@dmhall.co.uk  
01506 490404

## OBAN

oban-admin@dmhall.  
co.uk  
01631 564225

## PAISLEY

Enquiries are now dealt  
with at our Glasgow Hub.

## PERTH

perth@dmhall.co.uk  
01738 562100

## PETERHEAD

peterhead@dmhall.co.uk  
01779 470220

## ST ANDREWS

standrews@dmhall.co.uk  
01334 844826

## STIRLING

stirling@dmhall.co.uk  
01786 475785

